

1 / 3

<u>Field Resistor</u>	<u>Resistance</u>	<u>Field Resistor</u>	<u>Resistance</u>
<b>Resistor 137a</b>	<b>910 ohms</b>	<b>Resistor 137ab</b>	<b>110000 ohms</b>
<b>Resistor 137b</b>	<b>3830 ohms</b>	<b>Resistor 137ac</b>	<b>113000 ohms</b>
<b>Resistor 137c</b>	<b>5490 ohms</b>	<b>Resistor 137ad</b>	<b>121000 ohms</b>
<b>Resistor 137d</b>	<b>7150 ohms</b>	<b>Resistor 137ae</b>	<b>127000 ohms</b>
<b>Resistor 137e</b>	<b>15000 ohms</b>	<b>Resistor 137af</b>	<b>130000 ohms</b>
<b>Resistor 137f</b>	<b>15800 ohms</b>	<b>Resistor 137ag</b>	<b>137000 ohms</b>
<b>Resistor 137g</b>	<b>18200 ohms</b>	<b>Resistor 137ah</b>	<b>147000 ohms</b>
<b>Resistor 137h</b>	<b>30100 ohms</b>	<b>Resistor 137ai</b>	<b>150000 ohms</b>
<b>Resistor 137i</b>	<b>31600 ohms</b>	<b>Resistor 137aj</b>	<b>158000 ohms</b>
<b>Resistor 137j</b>	<b>36500 ohms</b>	<b>Resistor 137ak</b>	<b>165000 ohms</b>
<b>Resistor 137l</b>	<b>38300 ohms</b>	<b>Resistor 137al</b>	<b>169000 ohms</b>
<b>Resistor 137l</b>	<b>44200 ohms</b>	<b>Resistor 137am</b>	<b>174000 ohms</b>
<b>Resistor 137m</b>	<b>51000 ohms</b>	<b>Resistor 137an</b>	<b>182000 ohms</b>
<b>Resistor 137n</b>	<b>51100 ohms</b>	<b>Resistor 137ao</b>	<b>187000 ohms</b>
<b>Resistor 137o</b>	<b>53600 ohms</b>	<b>Resistor 137ap</b>	<b>191000 ohms</b>
<b>Resistor 137p</b>	<b>54900 ohms</b>	<b>Resistor 137aq</b>	<b>196000 ohms</b>
<b>Resistor 137q</b>	<b>56200 ohms</b>	<b>Resistor 137ar</b>	<b>200000 ohms</b>
<b>Resistor 137r</b>	<b>61900 ohms</b>	<b>Resistor 137as</b>	<b>205000 ohms</b>
<b>Resistor 137s</b>	<b>66500 ohms</b>	<b>Resistor 137at</b>	<b>210000 ohms</b>
<b>Resistor 137t</b>	<b>698 00 ohms</b>	<b>Resistor 137au</b>	<b>221000 ohms</b>
<b>Resistor 137u</b>	<b>71500 ohms</b>	<b>Resistor 137av</b>	<b>232000 ohms</b>
<b>Resistor 137v</b>	<b>73200 ohms</b>	<b>Resistor 137aw</b>	<b>243000 ohms</b>
<b>Resistor 137w</b>	<b>82500 ohms</b>	<b>Resistor 137ax</b>	<b>249000 ohms</b>
<b>Resistor 137x</b>	<b>88700 ohms</b>	<b>Resistor 137ay</b>	<b>470000 ohms</b>
<b>Resistor 137y</b>	<b>90900 ohms</b>	<b>Resistor 137az</b>	<b>680000 ohms</b>
<b>Resistor 137z</b>	<b>93100 ohms</b>	<b>Resistor 137ba</b>	<b>910000 ohms</b>
<b>Resistor 137aa</b>	<b>100000 ohms</b>	<b>Resistor 137bb</b>	<b>1M ohms</b>

Table 1

2/3




Fig. 1

3/3




Fig. 2